

FrameLink Release Notes

05/17/2006

Firmware v3.0 change description:

1	Fixed a problem where DMA Timeout errors may occur randomly after a reboot or power cycle.
---	--

Firmware v2.15 change description:

1	Implemented CC Pulse Generator.
2	Fixed problem where a DMA or UART Tx IRQ may get lost.

Driver v2.13 change description:

1	Fixed miscellaneous bugs related to UART processing.
2	Added support for CC Pulse Generator.
3	Added support for firmware v2.15.

Application v2.13 change description:

1	Miscellaneous GUI improvements made to menus and dialogs.
2	Added option to capture frames directly to disk without prior buffering in memory.
3	Added support for CC Pulse Generator.

SDK v2.13 change description:

1	Added CC Pulse Generator support - functions VCECLB_SetCCPulseGenerator(), VCECLB_GetCCPulseGenerator() and VCECLB_StartPulseGenerator() added.
2	Fixed problem where VCECLB_Prepare function is blocked by Snap during DMA timeout.