2.16   Left click "Next" to continue. The following message will appear:

Click "Yes" to continue.

2.17   Click "OK", then either enter or browse to: C:\Program Files\ImperX\VCE-Pro\Drivers\WDM
2.18   Click "OK".
2.19   This completes the installation for Windows 2000.

For additional information and the latest updates and downloads, please visit our website at www.imperx.com.

Use the following steps to install the VCE-PRO software supplied on a CD:

1.   If a version of VCE-PRO was previously installed on this machine, then you must first remove it:

To remove the application files:

1.1   Left mouse click on "Start"
1.2   Left mouse click on "Settings".
1.3   Left mouse click on "Control Panel".
1.4   Double left mouse click on "Add or Remove Programs".
1.5   Left mouse click on "Video Capture Essentials – Professional'.
1.6   Left mouse click on "Remove".
1.7   **If the 'VCE-PRO – InstallShield Wizard' pops-up, do the following: If not, go to step 1.8**
        Left mouse click on 'Remove'.
        Click 'Next'.
        Click 'Yes'.
        Click 'Finish'.
1.8   Left mouse click on "Yes".
1.9   Left mouse click on "Close".

2.   After having removed a previous version or if a version of VCE-PRO was NOT previously installed on this machine then:

**The first step is to install the application files:**

2.1   Insert the VCE-PRO CD into the appropriate drive; the setup.exe file will run automatically. Note: If it does not start automatically, left mouse click on to "Start", "Run", enter or browse to "(CD drive): setup.exe" and click "OK".
2.2   Wait for the "VCE-PRO - InstallShield Wizard" screen to appear.
2.3   Follow the on-screen instructions.
2.4   For Windows XP, the following message will appear:

For Windows 2000, the following message will appear:

2.5   Click "Continue Anyway" for XP, "Yes" for 2000.

2.6   When the following message appears, choose if you would like to register online by left clicking on "Yes" or "No".


If you choose "Yes", follow the on-screen instructions.

2.7   When prompted, select "Yes, I will restart my computer now".

After restarting the computer a New Hardware Found screen will come up: (the VCE-PRO card must be installed to perform the following steps)

Steps 2.8 through 2.14 are for Windows XP. For Windows 2000, go to Step 2.15

2.8   Wait for the system to prompt you with a "Found New Hardware Wizard" dialog box.

2.9   Under certain conditions, the following message may appear:

If this message appears, click "No, not this time", then "Next".

2.10   When the following message appears, select "Install the software automatically (Recommended)", then left click "Next".

2.11   For Windows XP, the following message will appear:

2.12   Click "Continue Anyway" to continue.

2.13   When "Click Finish to close the wizard" appears, Left click on "Finish".

2.14   This completes the installation for Windows XP.

To install the WDM driver for Windows 2000:

2.15   Wait for the system to prompt you with a "Found New Hardware Wizard" dialog box.