



HD-SDI Express

Release Notes – 1/08/2010

- Updated Application program to version 1.1.0.40 (from version 1.0.0.14).
- Updated Library/SDK to version 1.1.0.40 (from 1.0.0.14).
- Updated Driver to version 1.1.0.40 (from 1.0.8.152).
- Added support for Windows 64 bit XP and Vista operating systems.
- Added support for 32 bit application on 64 bit XP and Vista operating systems.
- Added support for Microsoft DirectShow, MathWorks MATLAB, MVTech HALCON

Software - 1.1.0.40		Changes from Software – 0.1.0.20	
Appl	1.1.0.40	Appl	1.0.0.14
Lib/SDK	1.1.0.40	Lib/SDK	1.0.0.14
Drv	1.1.0.40	Drv	1.0.8.152
1	Appl		Fixed AVI file saving
2	Appl		Text overlay on Vista fixed
3	Appl		Added Windows 64bit support
4	Appl		Changed video standard detection method
5	Appl		Added support for SD-SDI
6	Appl		Grabbing restart fixed
7	Appl		RGB24 mode set as default mode
8	Appl		GUI slowing-down in YUV mode fixed
9	Appl		Histogram panel in 16b color display mode fixed
10	SDK		Added Windows 64bit support
11	SDK		Added support of 32bit applications for 64bit driver
12	SDK		Changed video standard detection method
13	SDK		Grabbing restart fixed
14	Drv		Added Windows 64bit support
15	Drv		Added support of 32bit applications for 64bit driver
16	Drv		Digital Signature added to Vista driver
17	Drv		New DMA Buffers management implemented
18	Drv		Added interlace mode processing in driver
19	Drv		Added DrvManager application support