

LynxInstaller
v1.0.0.77
Release Notes

07/25/2006

LynxConfigurator v3.2.0.38 change description (changes from previous release v3.2.0.36):

1	Added 'WriteMode' token to CamConfig.ini to control Tx buffer length. WriteMode=1 sets buffer length to 1 WriteMode=0 sets buffer length to length of command
---	---

LynxTerminal v2.05 change description (changes from previous release v2.02):

1	ClSerial.ini file added for more flexible control of the serial interface parameters.
2	Fixed bug with Kermit upload on AMD x2 processor.